Operating Systems

· Microsoft™ Windows™ 98SE/Windows Me Japanese/English edition (For Windows 98SE and Windows Me, the HID function is not fully functional with the default class driver.)

· Microsoft Windows 2000 Professional Japanese/English edition

· Microsoft Windows XP Home/Professional Japanese/English edition (For Windows XP, use the latest version of the USB audio driver available from the Windows Internet site, or apply Service Pack 1 or later. See the Q310507 white paper available from Microsoft.)

· Microsoft Windows Vista™ Business Japanese/English edition

· Apple Computer Mac OS™ 9.1 or later Japanese/English edition

· Apple Computer Mac OS X 10.0 or later English edition

· Apple Computer Mac OS X 10.1 or later Japanese edition SP (For the Mac OS X 10.0 Japanese
  edition, plug and play does not work appropriately for USB audio devices.)